


**Corrigenda Geberit PP-KG Brochure**

**Page 6 & 7** (edition GEAU0033/12.08)


A print mistake on pages 6 & 7 may lead to some confusion and is herewith corrected and clarified. Black indicator (arrow) on Z2 values for PP-KG Junction 45° and PP-KG Junction 87° are not in line with Z2 value (mm) outlined on table below the picture. Red indicator (arrow) refers to correct Z2 value (mm) on table outlined below the picture.

**PP-KG Junction 45°**



Article No.	d [mm]	d1 [mm]	Z1 [mm]	Z2 [mm]	Z3 [mm]
391.106.PK.1	110	110	26	134	134
391.107.PK.1	160	110	2	168	159
391.108.PK.1	160	160	37	194	194
391.109.PK.1	200	160	19	221	218
391.117.PK.1	200	200	46	244	244

**PP-KG Junction 87°**



Article No.	d [mm]	d1 [mm]	Z1 [mm]	Z2 [mm]	Z3 [mm]
391.118.PK.1	110	110	59	62	62

Date of issue: September 9, 2009

The information contained is subject to change without notice. The information provided contains general description of the technical options available, which do not always apply to individual cases. The required features should therefore be individually clarified in accordance with individual situations at the time of proceeding.